

Sizing Process on P-H Diagram:





FIGURE 1






FIGURE 2A




FIGURE 2B

FIGURE 2D





FIGURE 2E




FIGURE 3A

FIGURE 3C





FIGURE 3B



7/16




FIGURE 4A

8/16




FIGURE 4B




FIGURE 4C




FIGURE 5





FIGURE 7




FIGURE 9




FIGURE 8




FIGURE 11





FIGURE 10

FIGURE 12






FIGURE 13

16/16




FIGURE 14




FIGURE 15




FIGURE 16A




FIGURE 16B